

VEHICLE INSPECTION REPORT

WD73CBX

NISSAN INTERSTAR F35 2.3 dci 135ps

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	54473
Cap Code	NIIN23523T6DTM2 2 L

Details

Location	Avonmouth	VIN	VNVM1000671645121	CAP Clean	£10,650.00
Reg. date	30/11/2023	Body Style	Panel Van L2	CAP Average	£9,875.00
Year	2023	Service history	Full	CAP Below	£8,500.00
Mileage	70,588 Miles Not Warranted	Service documents	Printout	Gearbox	MANUAL
Fuel Type	DIESEL	Last service date	02/04/2026	Gears	6
GVW	3500kg	Last service miles	60,001		
Colour	WHITE	MOT Due	29/11/2026		

AD BLUE, E/MIRRORS, SIDE LOAD DOOR

Tyres

NSF

NSR

OSF

OSR





Spare

Features


- Bluetooth connection
- Park assist camera
- Air conditioning
- Central locking
- Cruise control
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Front parking sensor
- Auxiliary input socket
- Drivers airbag
- Navigation system
- Digital radio
- Passenger airbag

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bonnet
Chipped
Multiple Chips




3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Door Mirror Assy nsf
Broken
Replace



5: Sill ns
Dented
Over 30mm

6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Scratched
Over 25mm Not Thru Paint

8: Qtr Panel Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



9: Qtr Panel nsr
Dented
Over 30mm

10: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



11: Bumper Rear
Scratched
Over 25mm Not Thru Paint

12: Door osr
Chipped
Multiple Chips



13: Door osr
Chipped
Edge Chip

14: Door nsr
Chipped
Edge Chip



15: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm

16: Qtr Panel osr
Dented
Over 30mm



17: Qtr Panel osr
Chipped
Over 5mm

18: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint




19: Roof
Scratched
Over 25mm Not Thru Paint

20: Door osf
Scratched
Over 25mm Not Thru Paint



21: Door osf
Chipped
Multiple Chips

22: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



23: Sill os
Chipped
Over 5mm

24: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



25: Seat Base Cover osf
Holed
Over 3mm

26: Centre Console Front
Scuffed
Over 25mm



27: Centre Console Front
Scuffed
Over 25mm

Interior

Carpet Condition		Average	Upholstery Condition	Average
Seat Condition		Average	Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK			
Sat nav	OK		Radio	OK