

VEHICLE INSPECTION REPORT

PO13EJF

Daf LF 55.220

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	01/07/2013	VIN	XLRAE55GF0L423791	Gearbox	AUTOMATIC
Year	2013	Body Style	Box Van	Axle Combi	4x2
Mileage	680,177 Km Warranted	Service history	Yes	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	31/01/2027	Rear Doors	Roller
Colour	RED	Cab Type	DAY CAB	Tail Lift	Cantilever

COLLECTED AS NON-RUNNER, TAIL LIFT REQUIRES ATTENTION

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Cruise control
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Cracked
Over 25mm



3: Panel Front
Poor Previous Repair
Poor Paint

4: Bumper Front
Dented
With Paint Damage



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Door osf
Scratched
Over 25mm Thru Paint

8: Door osf
Scratched
Over 25mm Not Thru Paint



9: Screen Front
Chipped
Over 10mm

10: Carpets Front
Torn
Over 10mm



11: Door Pad osf
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		