

VEHICLE INSPECTION REPORT

ETH665V

SCANIA 141

Imported

Inspection

Vehicle

VAT	Margin
V5	To Follow

Details

Reg. date	01/11/2018	Colour	RED	Gearbox	MANUAL
Year	1980	VIN	4215321	Axle Combi	6x4
Mileage	56,492 Km Not Warranted	Body Style	Tipper		
Fuel Type	Diesel	Cab Type	DAY CAB		

3 WAY TIPPER

Tyres

NSF

NSR

OSF

OSR

Spare

Photos

