

VEHICLE INSPECTION REPORT

WX61CEO

Ford Fiesta 1.4 TDCI 70PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	18/11/2011	VIN	WFORXXGAJRB77274	CAP Below	£400.00
Year	2011	Body Style	Car Derived Van	Gearbox	MANUAL
Mileage	107,192 Miles Warranted	MOT Due	20/06/2026	Gears	5
Fuel Type	Diesel	CAP Clean	£760.00		
Colour	WHITE	CAP Average	£600.00		

WARNING LIGHT ON DASH E/ MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Digital radio
- Radio/CD
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Roof
Chipped
Multiple Chips



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Other
N/A
N/A



5: Qtr Panel nsr
Chipped
Multiple Chips



6: Bumper Rear
Dented
With Paint Damage



7: Bumper Rear
Chipped
Multiple Chips



8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Qtr Panel osr
Dented
With Paint Damage



10: Door osf
Dented
With Paint Damage



11: Bumper Front
Scratched
Over 100mm Thru Paint



12: Door Pad osf
Soiled
Heavy



13: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	Fault
ABS light illuminated	OK	DPF light illuminated	OK